



DOCK Firmware Upgrades using USB

New firmware release notes Update for DOCKUCPT01 October 20th 2022

- Improving compatibility of power delivery on some laptops;
- Improving LAN connection issue;
- Improving USB compatibility issue for HP laptop;
- This FW version support products with SN# list below:
VM5085780D220C00001 to C01200;
VM5085780D228C00001 to C01200;
VM5085780D224C00001 to C01200.

Note:

This tool is better run on Windows10 or higher system.

To make driver install path correct, recommend put this folder under C: or D:.

This tool can only program one device at once. If there are more than one DOCKUCPT01 device, please disable all of them except which want to update FW